NOTIFICATION OF ASBESTOS-RELATED WORK

Date of Notification: 08/24/20)		DOSH Regsitration #045
CONTRACTOR/EMPLOYER NAME:	Karcher Environmental, Inc. (as shown on the registration certific	cate)	
HEADQUARTERS ADDRESS:	2300 E Orangewood Ave, Anahein	n, CA 92806	
CSLB LICENSE NUMBER:	481416 Phone Number:	(714)-385-1490	
TEMPORARY WORKSITE ADDRESS:	17631 Cameron Ave.	Huntington Beach	CA 92486
PRECISE LOCATION (intersection, bldg., floor, ro	om, apt no., etc.): Front do	oor and roof top	
TYPE OF SITE [.] Dwelling	NAME N/A		
Dwelling, store, school, office build	ling, etc.)	(Business/organization name unless re	sidential)
SITE OWNER CONTACT PERSON:	City of Hintington Beach	Deborah De Bow (714) 536-55	11
CERTIFIED SUPERVISOR NAME (Competent	person) Manuel Gonzale	Z	
QUALIFIED PERSON FOR CONDUCTING AIR	R MONITORING, RESPIRATOR F	IT TESTING, EVALUATION OF RESUL	TS & TESTS
Manuel Gonzalez			
CERTIFIED ASBESTOS CONSULTANT NAME	Alfered Mercado		C.A.C DOSH# 1566
PROJECTED JOB STARTING DATE:	8/25/20 TIME: 7AM		EST.END DATE 8/25/20
EMERGENCY : REASON:	am/pm		
TYPE OF ASBESTOS WORK			
CONSTR. MATERIAL	Destaurts		
	Root mastic		
AMOUNT sq. ft./linear	3 s/f		
PERCENTAGE ASB.	2%		
CLASS OF WORK (I, II intact, II Non-intact, III)	П		
Additional explanation			
3 stage decontamination	gative pressure enclosure		✓ Full disposable body protection
Class II decon, area	Mini-enclosure	Roofing waste disposal	HEPA PAPRS
Critical barriers	ve bags		HEPA 1/2 mask respirators
Vet methods	hanized removal methods	Manually Iowering	Arrine-Type C Protoctive Measure
(describe under "Other")	(Describe under "Other explanation"		(describe under "Other explanation")
Other practices/explanation:			,
EVALUATION OF EXPOSURE POTENTIAL: (c	ircle one): <0.1 fcc	0.1 f/cc <but<1.0 cc<="" f="" td=""><td>>1.0 f/cc</td></but<1.0>	>1.0 f/cc
Additional explanation:			

Send this completed notice to the nearest DOSH District Enforcement Office (go to www.dis.ca.gov/asp/DoskZipSearch.html) 24 hours prior to commencement of asbestos-related work (incl. separate phases of work, when different work practices are used, and if conducted at non-contiguous locations). Any change in the information provided shall be reported to the DOSH Districe Office at or before the time of change. If orally, confirm in writing immediately, but no later than 24 hours of the change.

Professional Environmental Consulting and Training Asbestos Lead Mold/Healthy Homes



Working for a clean environment 1101 California Ave, Suite 100 Corona, CA 92881 (951) 273-3410 info@allstate-services.com www.allstate-services.com

ASBESTOS SURVEY REPORT

a

17631 CAMERON LANE HUNTINGTON BEACH, CALIFORNIA

PREPARED FOR: LAURA HOLDER EEC ENVIRONMENTAL ONE CITY BOULEVARD WEST, SUITE 1800 ORANGE, CALIFORNIA 92868

PREPARED BY: ALLSTATE SERVICES 1101 CALIFORNIA AVENUE, SUITE 100 CORONA, CALIFORNIA 92881

APRIL 6, 2020

Professional Environmental Consulting and Training Asbestos Lead Mold/Healthy Homes



Working for a clean environment 1101 California Ave, Suite 100 Corona, CA 92881 (951) 273-3410 info@allstate-services.com www.allstate-services.com

April 6, 2020

Laura Holder EEC Environmental One City Boulevard West, Suite 1800 Orange, California 92868

RE: Asbestos Survey at 17631 Cameron Lane, Huntington Beach, California

Dear Ms. Laura Holder:

In accordance with your request and authorization, Allstate Services, has prepared the attached asbestos survey report. The sampling was conducted by Stacey J. Milano, a California Certified Asbestos Consultant.

Should you have any questions after reviewing the conclusions and recommendations contained within this report, please do not hesitate to contact the undersigned at (951) 273-3410. Allstate Services remains available to assist you in any way possible.

Sincerely, Allstate Services, LLC.

tacey milano

Stacey J. Milano California Certified Asbestos Consultant Certification No.: 01-2886

TABLE OF CONTENTS

1.	Scope of Work 1
2.	Building Description1
3.	Investigative Methods1
	3.1 Sampling Protocols1
	3.2 Laboratory Analytical Method2
4.	Results of Investigation2
5.	Recommendations5
6.	Limitations5

LIST OF TABLES

1.	Asbestos Survey Results	. 3
2.	Asbestos Containing Materials	.4

LIST OF APPENDICES

Appendix A - Floor Plan & Photographs
Appendix B - Laboratory Analytical Report
Appendix C - California Asbestos Certification

1. Scope of Work

Allstate Services was retained by EEC Environmental to conduct asbestos sampling and develop a scope of work for the subject site located at 17631 Cameron Lane in Huntington Beach, California. The sampling was conducted on April 3, 2020 and encompassed the interior and exterior areas of the building.

Prior to sampling, Stacey J. Milano, a California Certified Asbestos Consultant, conducted a walk through inspection and visual observation of all selected areas (excluding inaccessible areas such as locked rooms, tight pipe chases, wall cavities, concealed surfaces, etc.), to identify locations of suspect Asbestos Containing Materials (ACM) throughout the buildings. Upon completion of this inspection, samples of suspect ACM were collected, the material was described, and physical condition was assessed. Samples were then submitted to LA Testing to be analyzed for asbestos content by Polarized Light Microscopy (PLM). LA Testing is accredited under the National Voluntary Laboratory Accreditation Program (NVLAP).

The purpose of the sampling was to ascertain the presence of ACM in the buildings. The sampling did not consider such materials inaccessible to the consultant. Material not sampled should be considered suspect until proven otherwise by proper sampling techniques.

2. Building Description

The property tested is a single-story, single-family house. The building exterior consists of wood walls, wood door systems, wood window systems with window putty, roofing shingles, and penetration mastic. The building interior contains wood and plaster ceilings and walls, wood baseboards and cabinets, wood door and window systems, and floor tile and linoleum flooring with mastic.

3. Investigative Methods

A total of twenty-four (24) samples were collected throughout the structures. Samples were collected from each homogeneous material in selected areas. Sample locations were selected, to be true representations of most of materials in each homogeneous area. A unique number was assigned to each sample for identification. A total of fifty-nine (59) samples were analyzed, after layers were separated, and laboratory analytical reports can be found in Appendix B.

3.1 Sampling Protocol

This sampling followed the Asbestos Hazard Emergency Response Act (AHERA) guidelines to identify types of materials, sampling areas, and to determine the appropriate number of samples to be collected per homogeneous area.

The walk-through inspection and visual observation revealed the suspect ACM fall under Friable and Non-Friable Surfacing and Miscellaneous Materials.

3.2 Laboratory Analytical Method

The bulk samples were submitted to LA Testing in Huntington Beach, California to be analyzed for asbestos content by Polarized Light Microscopy as described on the "Interim Method of Determination of Asbestos in Bulk Insulation Samples" (40 CFR Ch. 1 Pr.763, appendix A to subpart F; F; July 1, 1987). LA Testing is an independent laboratory and, NVLAP-certified.

To ensure valid and reliable results, and to monitor samples during the collection, shipment, testing, and subsequent disposal phase of potentially asbestos-containing materials, Allstate Services has established a quality assurance program for the collection and submittal of bulk samples. This program consists of:

- Creation of a chain-of-custody form to keep track of the samples always by assigning responsibility for each phase of the data collection and analysis process to a specific person.
- Use of EPA-accredited laboratories that participate in the NVLAP sponsored by the National Institute of Standards and Technology for asbestos testing.

4. Results of Investigation

In accordance with the Environmental Protection Agency (EPA), any construction material containing more than one percent asbestos by weight is considered an Asbestos Containing Material (ACM). However, pursuant to Title 8 of the California Code of Regulations, ACCM is any manufactured construction material that contains more than one tenth of one percent (1/10 of 1%) asbestos by weight. In addition, according to policies developed for schools by the EPA, a homogeneous material is considered to contain asbestos when asbestos is detected in one or more samples of the subject material.

Table 1 summarizes the homogeneous areas inspected and sampled and presents the sample results. The laboratory results are presented in Appendix B. Following are the types, locations and the approximate quantities of ACM present in this facility. *Table 2* presents materials that are considered "asbestos containing materials" only.

TABLE 1Asbestos Survey Results17631 Cameron LaneHuntington Beach, California

Area	Area Code	Type of Material	Sample Number(s)	Sample Locations	Quantity	Sample Description	Condition	PLM Result	Percent
Building Interior	1	Plaster	P1 P2 P3	Living Room Bedroom Hall	2,650 Ft ²	Plaster (& Skim Coat & Drywall)	Damaged	ND ND ND	0% 0% 0%
Building Interior	2	Flooring	1FT1 1FT2 1FT3	Living Room Living Room Living Room	90 Ft ²	Light Gray 12"x12" Floor Tile & Mastic (& Leveler)	Damaged	ND ND ND	0% 0% 0%
Building Interior	3	Flooring	2FT1 2FT2 2FT3	Kitchen Kitchen Kitchen	110 Ft ²	Dark Gray 12"x12" Floor Tile & Mastic (& Leveler)	Damaged	ND ND ND	0% 0% 0%
Building Interior	4	Flooring	3FT1 3FT2 3FT3	Laundry Room Laundry Room	60 Ft ²	Tan 12"x12" Floor Tile & Mastic (& Leveler)	Intact	ND ND ND	0% 0% 0%
Building Interior	5	Flooring	L1 L2 L3	Bathroom Bathroom Bathroom	50 Ft ²	Beige Linoleum & Mastic (& Leveler)	Intact	ND ND ND	0% 0% 0%
Building Exterior	6	Putty	WP1 WP2 WP3	Exterior Window Exterior Window Exterior Window	10 Ft ²	Window Putty	Damaged	ND ND ND	0% 0% 0%
Building Exterior	7	Roof Shingles	RS1 RS2 RS3	Roof Roof Roof	1,200 Ft ²	Roofing Shingles (3 Layers)	Intact	ND ND ND	0% 0% 0%
Building Exterior	8	Mastic	PM1 PM2 PM3	Roof Roof Roof	3 Ft ²	Penetration Mastic	Intact	CH ND ND	2% 0% 0%

ND=None Detected CH=Chrysotile CR=Crocidolite A=Amosite N/A=Not Analyzed A/P=Assume Positive/See Floor Plan for sample locations. ACCM=Asbestos Containing Construction Material (This material has certain requirements for handling and notification per Cal-OSHA)

TABLE 2 ASBESTOS CONTAINING MATERIALS 17631 CAMERON LANE HUNTINGTON BEACH, CALIFORNIA

Area	Material	Quantity**	Material Location	Recommendations
Building Exterior	Penetration Mastic	3 Ft ²	Roof	Footnotes 2 & 4

**Quantities and exact locations of materials are estimates only. All bidders must verify on site the above-mentioned. Footnote 1: No action needed.

Footnote 2: Non-Friable asbestos; do not cut, sand, drill, polish, or damage the material; Operations and Maintenance Program is suggested. Footnote 3: Friable asbestos; remove, encapsulate, enclose, or repair any damaged material; Operation and Maintenance program is suggested Footnote 4: Remove affected asbestos containing materials prior to demolition/renovation. Materials may become friable when disturbed.

5. Recommendations

Based on the above conclusions, Allstate Services, LLC. recommends the following:

- Non-Friable asbestos; do not cut, sand, drill, polish, or damage the material; Operations and Maintenance Program is suggested.
- Remove affected asbestos containing materials prior to renovation/demolition.

6. Limitations

The conclusions and recommendations presented above are based on an agreed upon scope of work outlined in the above report. The services performed on the subject property included nondestructive sampling and excluded sampling of hidden materials or sampling from inaccessible areas such as locked rooms, tight piped chases, walled cavities, concealed surfaces, electric wiring, fire doors, hard segmentation materials, etc. It should be further understood that this report may not be a definitive study of the presence of Asbestos Containing Material in the facility, due to the nature of manufacturing, application, and location of ACM. The consultant makes no warranties or guarantees as to the accuracy, or completeness of information, obtained for information provided or compile by others. It is possible that information exists beyond the scope of this investigation. Also, changes in site use may have occurred sometime in the past due to variations in rainfall, temperature, water usage, economic, agricultural or other factors. Additional information that was not found or available to a consultant at the time of the writing of this report, may result in a modification of the conclusions and recommendations presented. This report is not a legal opinion. The services performed by consultant have been conducted in a manner consistent with care ordinarily exercised by members of our profession currently practicing under similar conditions. No other warranty, expressed or implied, is made.

Respectfully submitted;

Stacey milano

Stacey J. Milano California Certified Asbestos Consultant Certification No.: 01-2886 Appendix A Floor Plan & Photographs



17631 Cameron Lane, Huntington Beach, California













17631 Cameron Lane, Huntington Beach, California



Appendix B Laboratory Analytical Report

Tel/Fax: (714) 828-4999 / (714) 828-4944 http://www.LATesting.com / gardengrovelab@latesting.com

Attention:	Stacey Milano	Phone:	(951) 273-3410
	Allstate Services Environmental	Fax:	(951) 273-0138
	1101 California Ave	Received Date:	04/03/2020 1:05 PM
	Suite 100	Analysis Date:	04/04/2020
	Corona, CA 92881	Collected Date:	04/03/2020
Project:	17631 Cameron Lane, Huntington Beach, CA		

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

			Non-Asbe	estos	<u>Asbestos</u>
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Туре
P1-Skim Coat	Living room - plaster	Yellow Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0001		Homogeneous			
P1-Plaster	Living room - plaster	Tan Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0001A		Homogeneous			
P1-Drywall	Living room - plaster	Brown/White Fibrous	10% Cellulose	90% Non-fibrous (Other)	None Detected
332006491-0001B		Heterogeneous			
P2-Skim Coat	Bedroom 1 - plaster	Yellow Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0002		Homogeneous			
P2-Plaster	Bedroom 1 - plaster	Tan Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0002A		Homogeneous			
P2-Drywall	Bedroom 1 - plaster	Brown/White Fibrous	10% Cellulose	90% Non-fibrous (Other)	None Detected
532006491-0002B	I I - II	Heleiogeneous			New Datastad
P3-Skim Coat	Hall - plaster	Yellow Non-Fibrous		100% Non-fibrous (Other)	None Detected
552000491-0005	Liell plaster	Ton		100% New Sharve (Other)	Name Datastad
P3-Plaster	Hall - plaster	Ian Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
	Liell plaster	Drawn (A/hite		00% New Sharus (Other)	Name Datastad
232006491-0003B	nali - plaster	Fibrous	10% Cellulose	90% Non-Indrous (Other)	None Detected
1ET1-Eloor Tile	l iving room - floor tile	Grav		100% Non-fibrous (Other)	None Detected
332006491-0004	+ mastic	Non-Fibrous Homogeneous			None Deteoled
1FT1-Mastic	l iving room - floor tile	Yellow		100% Non-fibrous (Other)	None Detected
332006491-0004A	+ mastic	Non-Fibrous Homogeneous			
1FT2-Floor Tile	Living room - floor tile + mastic	Gray Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0005		Homogeneous			
1FT2-Mastic	Living room - floor tile + mastic	Yellow Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0005A		Homogeneous			
1FT2-Leveler	Living room - floor tile + mastic	Gray Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0005B		Homogeneous			
1FT3-Floor Tile	Living room - floor tile + mastic	Gray Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0006		Homogeneous			
1FT3-Mastic	Living room - floor tile + mastic	Yellow Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0006A		Homogeneous			

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

			Non-A	Asbestos	Asbestos
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
1FT3-Leveler	Living room - floor tile	Gray		100% Non-fibrous (Other)	None Detected
332006491-0006B	+ mastic	Non-Fibrous Homogeneous			
2FT1-Floor Tile	Kitchen - floor tile +	Gray Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0007	mastic	Homogeneous			
2FT1-Mastic	Kitchen - floor tile + mastic	Yellow Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0007A		Homogeneous			
2FT1-Leveler	Kitchen - floor tile + mastic	Gray Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0007B		Homogeneous			
2FT2-Floor Tile	Kitchen - floor tile + mastic	Gray Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0008		Homogeneous			
2FT2-Mastic	Kitchen - floor tile + mastic	Yellow Non-Fibrous		100% Non-fibrous (Other)	None Detected
252008491-0008A	Kitaban flaar tila +	Cray		100% Non fibrous (Othor)	Nono Detected
332006491-0008B	mastic	Non-Fibrous Homogeneous			
2FT3-Floor Tile	Kitchen - floor tile +	Grav		100% Non-fibrous (Other)	None Detected
332006491-0009	mastic	Non-Fibrous Homogeneous			
2FT3-Mastic	Kitchen - floor tile +	Yellow		100% Non-fibrous (Other)	None Detected
332006491-0009A	mastic	Non-Fibrous Homogeneous			
2FT3-Leveler	Kitchen - floor tile +	Gray		100% Non-fibrous (Other)	None Detected
332006491-0009B	mastic	Non-Fibrous Homogeneous			
3FT1-Floor Tile	Kitchen - floor tile +	Gray		100% Non-fibrous (Other)	None Detected
332006491-0010	mastic	Non-Fibrous Homogeneous			
3FT1-Mastic	Kitchen - floor tile + mastic	Yellow Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0010A		Homogeneous			
3FT1-Leveler	Kitchen - floor tile + mastic	Gray Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0010B		Homogeneous			
3FT2-Floor Tile	Kitchen - floor tile + mastic	Gray Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0011		Homogeneous			
3FT2-Mastic	Kitchen - floor tile + mastic	Yellow Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0011A	Kitabara dia antia a	Homogeneous			News Detected
3F I 2-Leveler	Kitchen - floor tile + mastic	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
3ET3 Floor Tile	Kitchen - floor tile +	Grav		100% Non-fibrous (Other)	None Detected
332006491-0012	mastic	Non-Fibrous Homogeneous			None Deletted
3FT3-Mastic	Kitchen - floor tile +	Yellow		100% Non-fibrous (Other)	None Detected
332006491-0012A	mastic	Non-Fibrous Homogeneous			
3FT3-Leveler	Kitchen - floor tile + mastic	Gray Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0012B		Homogeneous			

Initial report from: 04/04/2020 15:02:43

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

			Non-Asbe	stos	Asbestos
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Туре
L1-Linoleum	Bathroom - linoleum + mastic	Gray/Beige Fibrous	10% Cellulose 2% Glass	88% Non-fibrous (Other)	None Detected
332006491-0013		Heterogeneous			
L1-Mastic	Bathroom - linoleum + mastic	Yellow Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0013A		Homogeneous			
L1-Leveler	Bathroom - linoleum + mastic	Gray Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0013B		Homogeneous			
L2-Linoleum	Bathroom - linoleum + mastic	Gray/Beige Fibrous	5% Cellulose 3% Glass	92% Non-fibrous (Other)	None Detected
332006491-0014		Heterogeneous			
L2-Mastic	Bathroom - linoleum + mastic	Yellow Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0014A		Homogeneous			N
L2-Leveler	Bathroom - Inoleum + mastic	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
	Dethroom lineloum	Crav/Baiga		85% Non fibrous (Other)	None Detected
332006491-0015	mastic	Fibrous Heterogeneous	3% Glass		None Delected
I 3-Mastic	Bathroom - linoleum +	Yellow		100% Non-fibrous (Other)	None Detected
332006491-0015A	mastic	Non-Fibrous Homogeneous			None Deteoled
l 3-l eveler	Bathroom - linoleum +	Grav		100% Non-fibrous (Other)	None Detected
332006491-0015B	mastic	Non-Fibrous Homogeneous			
WP1	Exterior - window putty	White Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0016		Homogeneous			
WP2	Exterior - window putty	White Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0017		Homogeneous			
WP3	Exterior - window putty	White Non-Fibrous		100% Non-fibrous (Other)	None Detected
332006491-0018		Homogeneous			
R1-Shingle 1	Exterior - roofing	Brown/Gray/Black Fibrous	15% Glass	85% Non-fibrous (Other)	None Detected
532000491-0019	Enterior motion	Received Press	40% Olass		Nexe Detected
332006491-0019A	Extendi - rooning	Fibrous Heterogeneous	12% Glass	86% NON-HOROUS (Other)	None Detected
P1 Shingle 3	Exterior - roofing	Grav/Black	10% Glass	90% Non-fibrous (Other)	None Detected
332006491-0019B	Extends - rooming	Fibrous	10 /0 Glass		None Delected
R2-Shingle 1	Exterior - roofing	Brown/Gray/Black	15% Glass	85% Non-fibrous (Other)	None Detected
332006491-0020		Fibrous Heterogeneous			
R2-Shingle 2	Exterior - roofing	Brown/Black Fibrous	10% Glass	90% Non-fibrous (Other)	None Detected
332006491-0020A		Heterogeneous			
R2-Shingle 3	Exterior - roofing	Gray/Black Fibrous	15% Glass	85% Non-fibrous (Other)	None Detected
332006491-0020B		Heterogeneous			
R3-Shingle 1	Exterior - roofing	Brown/Gray/Black Fibrous	10% Glass	90% Non-fibrous (Other)	None Detected
332006491-0021		Heterogeneous			

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

			Non-Asbe	stos	Asbestos
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Туре
R3-Shingle 2	Exterior - roofing	Brown/Black Fibrous	15% Glass	85% Non-fibrous (Other)	None Detected
332006491-0021A		Heterogeneous			
R3-Shingle 3	Exterior - roofing	Gray/Black Fibrous	15% Glass	85% Non-fibrous (Other)	None Detected
332006491-0021B		Heterogeneous			
PM1	Roof - penetration mastic	Black Fibrous	10% Cellulose	88% Non-fibrous (Other)	2% Chrysotile
332006491-0022		Homogeneous			
PM2	Roof - penetration mastic	Black Fibrous	15% Cellulose	85% Non-fibrous (Other)	None Detected
332006491-0023		Homogeneous			
PM3	Roof - penetration mastic	Gray/Tan/Black Fibrous	5% Cellulose 2% Glass	93% Non-fibrous (Other)	None Detected
332006491-0024		Heterogeneous			

Analyst(s)

Mindy Le (59)

aughter lutar

Michael DeCavallas, Laboratory Manager or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method"), but augmented with procedures outlined in the 1993 ("final") version of the method. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. All samples received in acceptable condition unless otherwise noted. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. EMSL recommends gravimetric reduction for all non-friable organically bound materials prior to analysis. Estimation of uncertainty is available on request.

Samples analyzed by LA Testing Huntington Beach, CA NVLAP Lab Code 101384-0, CA ELAP 1406

Initial report from: 04/04/2020 15:02:43

#332006491

BULK DI MILLE REVUEDI I UNII

Alls 1101 Calif Cor Ph: (951) 273-3 Results to <u>inf</u> <u>stravers@</u> <u>smilano@</u>	state Services ornia Ave, Sui ona, CA 92881 3410 Fax: (951) o@allstate-services allstate-services	te 100 273-3411 ices.com .com, s.com	DATE: 4/3/2020 Turn Around Time hr/12hr/24hr/48hr/Ext ANALYZE TO 1 ST POSITIVE? YES NO				
CONTACT: Stacey M	ilano		PLM: Standard Point Count				
SITE: 17631 Came Huntington I	JOB: ron Lane Beach, CA		AA/Flame AA/Furnace ICP METALS:				
SAMPLE NUMBER	DATE COLLECTED	SAMPLE LO	OCATION/DESCRIPTION				
PL	4/3/20	Una Room - Plaster					
PZ		Bedraom 1 - Plaster					
P3		Hall	- Plaster				
IFT)		Uvina	Room - Floortile & Mastic				
IFT2	alit Marine	UVING	Iving Room - Floor tile + Mastic				
IFT3		Luing	Living Room - Floor tile & Mastic				
2FT1		Kitche	chen - Floor tile & mastic				
2FT2		Kitch	tchen - Floor tile + Mastic				
2FT3		Kitche	hen - Floor tile " Mastic				
3FT1	Som	Kitch	en - Floorfile & Mastic				
Sample by:Stacey Mila	no Stace	enmile	Date: 4/3/2020 Time:				
Relinquished by: Date/Time:	Milan +	3/20	Received by: EM (wi) Date/Time: 4/3/20 1:05 PM Sealed Condition (circle one) YES/NO				
Relinquished by: Date/Time:			Received by: Date/Time:				
		page	10f 3				

#332006491

BULK SAMPLE REQUEST FORM

Alls 1101 Calife Core Ph: (951) 273-3 Results to infe stravers@: smilano@:	state Services ornia Ave, Sui ona, CA 92881 6410 Fax: (951) o@allstate-serv allstate-services allstate-services	te 100) 273-3411 (ices.com s.com, s.com	DATE: 4/3/2020 Turn Around Time hr/12hr/24hr/48hr/Ext ANALYZE TO 1 ST POSITIVE? YES NO			
CONTACT: Stacey M	ilano		PLM: Standard Point Count			
SITE: 17631 Came Huntington I	JOB: ron Lane Beach, CA		TEM: QUAL. / QUANT. / WATER AA/Flame AA/Furnace ICP METALS:			
SAMPLE NUMBER	DATE COLLECTED	SAMPLE LOO	CATION/DESCRIPTION			
3FTA 3FT3	4/3/20	Kitchen - Floor tile & Mastic Kitchen - Floor tile & Mastic				
LI		Bathr	oom- Lenoleum & mastic			
L2	A State State	Bathro	om- Unoleum + Mastic			
L3	and the second second	Bathrox	throom - Linoleum + Mastic			
WP1		Exter	Exterior - Window Putty			
WP 2		Exter	or Window Putty			
WP 3	ng patiers	Exteri	10r - Window Putty			
R)		Exter	nor - Roofing			
R2	139m	Exter	rior - Roofing			
Sample by:Stacey Mila	no Stace	Melano	Date: 4/3/2020 Time:			
Relinquished by: Date/Time:	Melan	4/3/20	Received by: Date/Time: Sealed Condition (circle one) YES / NO			
Relinquished by: Date/Time:			Received by: Date/Time:			

page 2 of 3

#332006491

	Bl	ULK	SAMP	LE	RE	OUEST	FORM
--	----	-----	------	----	----	-------	------

Alls 1101 Calify Core Ph: (951) 273-3 Results to inf stravers@j smilano@j CONTACT: Stacey M P.O. #: SITE: 17631 Came Huntington I	state Services ornia Ave, Sui ona, CA 92881 3410 Fax: (951) o@allstate-services allstate-services ilano JOB: rron Lane Beach, CA	ite 100) 273-3411 rices.com s.com, s.com	DATE: 4/3/2020 Turn Around Time hr/12hl/24hr/48hr/Ext ANALYZE TO 1 ST POSITIVE? YES NO PLM: Standard Point Count TEM: QUAL. / QUANT. / WATER AA/Flame AA/Furnace ICP METALS:			
SAMPLE NUMBER	DATE COLLECTED	SAMPLE LOO	CATION/DESCRIPTION			
R3 Pm1 Pm2 Pm3	4/3/20 1 39m	Exter Roof Roof- Roof-	- Penetration Mastic Penetration Mastic Penetration Mastic			
Sample by:Stacey Mila Relinquished by: Date/Time:	ano <u>Stare</u> Smilain	y Juliani 4/3/20	Date: 4/3/2020 Time: Received by: Date/Time: Sealed Condition (circle one) YES / NO			
Relinquished by: Date/Time:			Received by: Date/Time:			

Appendix C California Asbestos Certification

State of California Division of Occupational Safety and Health Certified Asbestos Consultant

Professional Environmental Consulting and Training Asbestos Lead Mold/Healthy Homes

Working for a clean environment 1101 California Ave, Suite 100 Corona, CA 92881 (951) 273-3410 info@allstate-services.com www.allstate-services.com

LEAD-BASED PAINT INSPECTION

a

17631 CAMERON LANE HUNTINGTON BEACH, CALIFORNIA

PREPARED FOR: LAURA HOLDER EEC ENVIRONMENTAL ONE CITY BOULEVARD WEST, SUITE 1800 ORANGE, CALIFORNIA 92868

PREPARED BY: STACEY J. MILANO INSPECTOR/ASSESSOR CERTIFICATION #LRC-00000083

APRIL 6, 2020

Professional Environmental Consulting and Training Asbestos Lead Mold/Healthy Homes

Working for a clean environment 1101 California Ave, Suite 100 Corona, CA 92881 (951) 273-3410 info@allstate-services.com www.allstate-services.com

April 6, 2020

Laura Holder EEC Environmental One City Boulevard West, Suite 1800 Orange, California 92868

RE: Lead-based paint inspection at 17631 Cameron Lane, Huntington Beach, California

Dear Ms. Laura Holder:

In accordance with your request and authorization, Allstate Services conducted a lead-based paint inspection at 17631 Cameron Lane in Huntington Beach, California on April 3, 2020. The on-site work was conducted by Stacey J. Milano, a California Certified Lead Inspector/Assessor.

If you need any further assistance after reviewing your report, please do not hesitate to contact me. Allstate Services remains available to assist you in anyway possible.

Sincerely, Allstate Services, LLC.

Stacey Jmilano

Stacey J. Milano Inspector/Assessor #: LRC-00000083

TABLE OF CONTENTS

Desci	<u>ription</u>	<u>Page</u>
1.0	Testing Methodology	1
2.0	Building Description	2
3.0	Lead-Based Paint Findings	2
4.0	California State Requirements	3
5.0	Recommendations	3
6.0	Federal Requirements	4
7.0	OSHA Compliance	4

Appendices

- A. Summary Inspection Notice
- B. Detailed XRF Testing Results
- C. Floor Plan
- D. Inspector/Assessor Certifications
- E. CDPH Form 8552 Lead Hazard Evaluation Report

1.0 TESTING METHODOLOGY

Lead-based paint testing was conducted using portable x-ray fluorescence (XRF) spectrum analyzer, Model LPA-1, Manufactured by Radiation Monitoring Devices. The LPA-1 is calibrated to measure the K-shell x-ray emissions of lead. The K-shell normally used for paint analysis because it measures lead in all layers of paint films, including the lower layers where higher concentrations of lead are usually found.

Lead-based paint testing was conducted in accordance with *Title 17, California Code of Regulations, Division 1, Chapter 8, Accreditation, Certification, and Work Practice in Lead Related Construction, Section 36000* and the United States Department of Housing and Urban Developments *Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing, Chapter 7 Lead-Based Paint Inspections*, as published in June 1995 and revised in 1997.

The purpose of this inspection is to identify surfaces, which contain lead-based paint as per California regulations, the *HUD Guidelines and section 403 of the Toxic Substances Control Act*.

The state of California, HUD and the EPA currently define lead-based paint as a paint or other surface coating which contains lead equal to or greater than 1.0 milligrams of lead per square centimeter of surface area (mg/cm²).

XRF readings were taken using the "Quick" mode of the LPA-1. The "Quick" mode measurements have no predetermined testing length, and automatically adjust to account for various types of substrates and materials densities. The precision of the XRF readings is proportional to the square root of the number of x-rays counted by the scanner. The longer the test, the higher the level of precision as compared against the set threshold level of 1.0 mg/cm².

In the "quick" mode, the LPA-1 tests until a K-shell result is indicated as either positive or negative, compared to the threshold level based on the current precision of the test. Correction for paint matrix and substrate effects is performed automatically. The correction function is based on measurements performed by the manufacturer with NIST paint film standards laid over a variety of substrates typically encountered in construction.

Based on the XRF Performance Characteristic Sheet (PCS) jointly released by HUD and EPA (effective October 25, 2006), there is no inconclusive range and the Threshold is 1.0 mg/cm². Results are classified as positive if they are at or greater than the threshold as listed. Results are classified as negative if they are less than the listed threshold. No substrate correction is required for testing using the "Quick" mode.

XRF readings were made on testing combinations in all room equivalents in an effort to test typical materials which are representative of the room equivalent. Testing combinations were tested non-destructively by holding the LPA-1 against the surface being tested. At each XRF sample location the LPA-1 shutter is opened, and one reading was made using the "Quick" testing mode. Results of each test were read from the digital display of the instrument console and recorded on the Detailed XRF Testing Results attached in Appendix B.

To ensure that the XRF equipment was working properly, various quality control tests were performed before, during and after the on-site work. At the beginning of the workday, three start up validation measurements were made in the "Quick" mode, using the calibration check standard associated with the particular LPA-1 that was used. This painted standard contains a known quantity of lead and allows the XRF operator to determine whether the instrument is functioning within acceptable tolerance ranges for accuracy and precision, as determined by the manufacturer.

In addition to the three starts up tests, calibration readings were taken on the red 1.02 mg/cm² Standard Reference Material (SRM) paint film, developed by the National Institute of Standards and Technology (NIST). Results of each reading, along with computed readings averages were recorded on the XRF Calibration Form and compared against the calibration tolerance range defined the LPA-1 PCS. This calibration check was also performed after four hours and at the end of the day. The quality control tests taken during testing at the subject property were within the acceptable performance range prescribed by the PCS and by the XRF equipment manufacturer. Documentation of the quality control calibration check is included in Appendix B, following the detailed testing data.

2.0 BUILDING DESCRIPTION

The property tested is a single-story, single-family house. The building exterior consists of wood walls, wood door systems, eaves, rafters, fascia, and window systems. The building interior contains wood and plaster ceilings and walls, wood baseboards and cabinets, and wood door and window systems.

3.0 LEAD-BASED PAINT FINDINGS

Lead-based paint was found at or above the threshold level of 1.0 mg/cm^2 on the following components:

• Interior door frame

Please see Appendix A - XRF Positive Summary Report for a complete list of positive components and specific locations.

4.0 CALIFORNIA STATE REQUIREMENTS

Allstate Services is required under California regulations (Title 17, CCR, Division 1, Chapter 8) to notify California Department of Public Health that a lead hazard evaluation survey was conducted at the subject property.

Please see Appendix E or CDPH Form 8552, Lead Hazard Evaluation Report.

5.0 RECOMMENDATIONS

If this building undergoes renovation in the future, personnel performing the construction work should be properly trained in lead-related construction. California regulations define lead-related construction work as, "Construction, alteration, painting, demolition, salvage, renovation, repair, or maintenance of any residential, public or commercial building, including preparation and cleanup that, by using or disturbing lead containing material or soil, may result in significant exposure of individuals to lead." California has a certification process for lead related construction workers. To receive a list of certified individuals, you may contact the Lead Accreditation and Certification Unit Hotline at (800) 597-5323.

There are different methods of addressing lead hazards. These methods include:

- Abatement A measure or set of measures designed to permanently eliminate lead-based paint hazards or lead-based paint. There are different methods of abatement:
 - <u>Replacement</u>: Removing the old component and installing a new non-lead containing component. Replacement is best suited for components that are easily removed. This includes doors, windows, trim, etc.
 - Enclosure:Covering a surface with a durable mechanically affixed, dust
tight material, such as drywall, paneling, aluminum siding, etc.
Enclosure is best used on walls, ceilings, floors, and some
exterior components.
 - Removal:Removing the paint from the substrate. This is accomplished
by wet scraping, using power tools with special HEPA vacuum
attachments, heat guns, and chemical stripping either on or off
site. Paint removal is best suited when a component is to be
preserved or when a component cannot be easily replaced or
enclosed. Lead-based paint encapsulant products must have a
minimum of twenty years warranty.
 - <u>Encapsulation</u>: The process that makes lead-based paint inaccessible by providing a barrier between the lead-based paint and the environment. This barrier is formed using a liquid applied coating or an adhesive bonded covering material. Encapsulation is best used on walls and ceilings. Please note that ordinary lead-free paint is not considered an encapsulation.
- **Interim Controls** A set of measures designed to temporarily reduce human exposure or likely exposure to lead-based paint hazards. Interim controls include specialized cleaning, repairs, maintenance, painting, temporary containment, ongoing monitoring of lead-based paint hazards or potential hazards and the establishment and operation of management and resident education programs. Interim controls should be used only if full abatement is not feasible. Reducing the hazards can be accomplished by simply keeping the painted surfaces intact and through specialized cleaning methods. If abatement cannot take place soon, interim controls should be implemented and maintained until full abatement can be made.

As previously stated, any activities involving lead hazard control and/or lead abatement must be performed by certified individuals.

6.0 FEDERAL REQUIREMENTS

A copy of this summary must be provided to new lessees (tenants) and purchaser of this property under federal law (24 CFR part 35 and 40 CFR part 745) before they become obligated under a lease or sales contract. The complete report must also be provided to new purchasers and it must be made available to tenants. Landlord (lessors) and sellers are also required to distribute an educational pamphlet approved by the U. S. Environmental Protection Agency and include standard warning language in their lease or sales contracts to ensure that parents have the information they need to protect their children from lead-based paint hazards.

7.0 OSHA COMPLIANCE

OSHA Regulations (Title 8 CCR Section 1532.1 and 29 CFR 1926.62) apply to all construction work where an employee may be occupationally exposed to lead, and therefore may be applicable to renovation or demolition projects involving paints with any concentration of lead.

It should be noted that "Lead-Based Paint Inspection" is a survey to discover the existence of leadbased paint only, which is defined as paint or other coating with lead levels of 1.0 mg/cm² or 0.5%. There are many other building materials, which may contain lead in the average building. When conducting construction activities, which disturb lead in any amount or create an exposure to workers, the employer is required to provide worker protection and conduct exposure assessments. All employers should consult Federal OSHA Regulations at 29 CFR 1926.62 and Cal-OSHA Regulations at Title 8, 1532.1, "Lead in Construction" standards for complete requirements.

APPENDIX A SUMMARY INSPECTION NOTICE

Professional Environmental Consulting and Training Asbestos Lead Mold/Healthy Homes

Working for a clean environment 1101 California Ave, Suite 100 Corona, CA 92881 (951) 273-3410 info@allstate-services.com www.allstate-services.com

Summary Notice of Lead-Based Paint Inspection

Address/location of property or structure this summary notice applies to: 17631 Cameron Lane Huntington Beach, California

Lead-based paint inspection description: Date of inspection: *April 3, 2020*

Summary of inspection results (check all that apply):

- A. _____ No lead-based paint was found.
- B. <u>X</u> Lead-based paint was found.
- C. <u>X</u> A brief summary of the findings of the inspection is provided below (required if leadbased paint is found)

See positive summary table.

Prepared by: Stacey J. Milano

Certification Number: #LRC-00000083

	POSITIVE XRF SUMMARY REPORT										
	17631 Cameron Lane, Huntington Beach, California										
Sample	Room Side Lead Quantities Sample Area Fourivalent Tested Component Substrate Color Condition cm²) Results Area Comments										
25	Interior	Rm. 1-Entry	А	Door Frame	Wood	White	Deteriorated	1.3	Positive	1 Each	
**Quantity es	stimation	s of leaded materials are provid	led for budge	et considerations only and	I should be verifie	ed onsite by b	idders.				

APPENDIX B DETAILED XRF TESTING RESULTS

DETAILED XRF TESTING RESULTS											
17631 Cameron Lane, Huntington Beach, California											
		Room	Side					Lead (mg/		Quantities For Entire	
Sample	Area	Equivalent	Tested	Component	Substrate	Color	Condition	cm ²)	Results	Area	Comments
1	Exterior	Building Exterior	A	Wall	Wood	White	Deteriorated	0.4	Negative		
2	Exterior	Building Exterior	A	Door	Wood	White	Intact	0.2	Negative		
3	Exterior	Building Exterior	A	Door Frame	Wood	White	Intact	0.3	Negative		
4	Exterior	Building Exterior	A	Window Screen	Wood	Brown	Intact	0.3	Negative		
5	Exterior	Building Exterior	A	Window Frame	Wood	Brown	Intact	0.2	Negative		
6	Exterior	Building Exterior	A	Window Sash	Wood	White	Deteriorated	0.5	Negative		
7	Exterior	Building Exterior	A	Corner Board	Wood	Brown	Intact	0.3	Negative		
8	Exterior	Building Exterior	A	Corner Board	Wood	White	Intact	0.2	Negative		
9	Exterior	Building Exterior	A	Fascia	Wood	White	Deteriorated	0.3	Negative		
10	Exterior	Building Exterior	В	Wall	Wood	White	Deteriorated	0.3	Negative		
11	Exterior	Building Exterior	В	Cabinet	Wood	White	Deteriorated	0.3	Negative		
12	Exterior	Building Exterior	В	Eave	Wood	White	Deteriorated	0.3	Negative		
13	Exterior	Building Exterior	В	Rafter Tail	Wood	White	Deteriorated	0.2	Negative		
14	Exterior	Building Exterior	В	Foundation	Concrete	White	Deteriorated	0.3	Negative		
15	Exterior	Building Exterior	C	Wall	Wood	White	Deteriorated	0.3	Negative		
16	Exterior	Building Exterior	C	Door	Metal	White	Deteriorated	0.3	Negative		
17	Exterior	Building Exterior	С	Door Frame	Wood	Brown	Intact	0.1	Negative		
18	Exterior	Building Exterior	D	Wall	Wood	White	Intact	0.2	Negative		
19	Exterior	Building Exterior	C	Shed	Wood	White	Deteriorated	0.3	Negative		
20	Interior	Rm. 1-Entry	A	Wall	Wood	White	Deteriorated	0.2	Negative		
21	Interior	Rm. 1-Entry	В	Wall	VVood	vvnite	Deteriorated	0.1	Negative		
22	Interior	Rm. 1-Entry	C	Wall	VVOOD	VVnite	Deteriorated	0.3	Negative		
23	Interior	RIII. I-EIIIIY		Vall	DOOV	Drown	Detenorated	0.1	Negative		
24	Interior	Rill. I-Elluy	A	Door Frame	Wood	Mbito	Deteriorated	0.0	Desitive	1 Each	
20	Interior	Rm 1 Entry	A C	Door Frame	Wood	White	Deteriorated	1.3	Nogativo	I Each	
20	Interior	Pm 1 Entry	C C	Window Framo	Wood	White	Deteriorated	0.0	Negative		
21	Interior	Rm 1-Entry	0 C	Window Sash	Wood	White	Deteriorated	0.2	Negative		
20	Interior	Rm 1-Entry	D	Window Sash	Wood	White	Deteriorated	0.1	Negative		
30	Interior	Rm 1-Entry	<u>л</u>	Window Frame	Wood	White	Deteriorated	0.3	Negative		
31	Interior	Rm. 1-Entry		Ceiling	Wood	White	Deteriorated	0.2	Negative		
32	Interior	Rm. 2-Living Room	А	Wall	Plaster	White	Deteriorated	0.1	Negative		
33	Interior	Rm. 2-Living Room	В	Wall	Plaster	White	Deteriorated	0.3	Negative		
34	Interior	Rm. 2-Living Room	C	Wall	Plaster	White	Deteriorated	0.4	Negative		
35	Interior	Rm. 2-Living Room	D	Wall	Plaster	White	Deteriorated	-0.1	Negative		
36	Interior	Rm. 2-Living Room	A	Baseboard	Wood	White	Deteriorated	0.2	Negative		
37	Interior	Rm. 2-Living Room	A	Door Frame	Wood	White	Deteriorated	0.1	Negative		
38	Interior	Rm. 2-Living Room	В	Window Frame	Wood	White	Deteriorated	0.2	Negative		
39	Interior	Rm. 2-Living Room	В	Window Sash	Wood	White	Intact	0.2	Negative		
40	Interior	Rm. 2-Living Room		Ceiling	Plaster	White	Deteriorated	-0.4	Negative		
41	Interior	Rm. 2-Living Room	С	Upper Cabinet	Plaster	White	Deteriorated	-0.2	Negative		
42	Interior	Rm. 3-Hall	A	Wall	Plaster	White	Deteriorated	-0.1	Negative		
43	Interior	Rm. 3-Hall	В	Wall	Plaster	White	Deteriorated	0.0	Negative		

DETAILED XRF TESTING RESULTS											
17631 Cameron Lane, Huntington Beach, California											
		Room	Side					Lead (mg/		Quantities For Entire	
Sample	Area	Equivalent	Tested	Component	Substrate	Color	Condition	cm²)	Results	Area	Comments
44	Interior	Rm. 3-Hall	С	Wall	Plaster	White	Deteriorated	-0.2	Negative		
45	Interior	Rm. 3-Hall	D	Wall	Plaster	White	Deteriorated	-0.3	Negative		
46	Interior	Rm. 3-Hall	В	Baseboard	Wood	White	Deteriorated	-0.1	Negative		
47	Interior	Rm. 3-Hall	D	Door	Wood	White	Deteriorated	0.2	Negative		
48	Interior	Rm. 3-Hall	D	Door Frame	Wood	White	Deteriorated	0.2	Negative		
49	Interior	Rm. 3-Hall		Ceiling	Plaster	White	Deteriorated	0.4	Negative		
50	Interior	Rm. 3-Hall	D	Cabinet	Wood	White	Deteriorated	0.0	Negative		
51	Interior	Rm. 4-Bedroom 1	A	Wall	Plaster	White	Deteriorated	0.2	Negative		
52	Interior	Rm. 4-Bedroom 1	В	Wall	Plaster	White	Deteriorated	-0.3	Negative		
53	Interior	Rm. 4-Bedroom 1	С	Wall	Plaster	White	Deteriorated	0.0	Negative		
54	Interior	Rm. 4-Bedroom 1	D	Wall	Plaster	White	Deteriorated	0.3	Negative		
55	Interior	Rm. 4-Bedroom 1	В	Baseboard	Wood	White	Deteriorated	-0.1	Negative		
56	Interior	Rm. 4-Bedroom 1	С	Door Frame	Wood	White	Deteriorated	-0.3	Negative		
57	Interior	Rm. 4-Bedroom 1	A	Window Frame	Wood	White	Deteriorated	0.0	Negative		
58	Interior	Rm. 4-Bedroom 1	A	Window Sash	Wood	White	Deteriorated	0.0	Negative		
59	Interior	Rm. 4-Bedroom 1		Ceiling	Plaster	White	Deteriorated	0.3	Negative		
60	Interior	Rm. 4-Bedroom 1	С	Closet Shelf	Wood	White	Deteriorated	-0.4	Negative		
61	Interior	Rm. 5-Bathroom	A	Wall	Plaster	White	Deteriorated	0.0	Negative		
62	Interior	Rm. 5-Bathroom	В	Wall	Plaster	White	Deteriorated	0.2	Negative		
63	Interior	Rm. 5-Bathroom	С	Wall	Ceramic Tile	Pink	Intact	>9.9	Positive		Not a Painted Surface
64	Interior	Rm. 5-Bathroom	D	Wall	Ceramic Tile	White	Intact	>9.9	Positive		Not a Painted Surface
65	Interior	Rm. 5-Bathroom	В	Door	Wood	White	Deteriorated	0.2	Negative		
66	Interior	Rm. 5-Bathroom	В	Door Frame	Wood	White	Deteriorated	0.3	Negative		
67	Interior	Rm. 5-Bathroom	D	Window Frame	Wood	White	Deteriorated	0.0	Negative		
68	Interior	Rm. 5-Bathroom	D	Window Sash	Wood	White	Deteriorated	0.4	Negative		
69	Interior	Rm. 5-Bathroom		Ceiling	Plaster	White	Deteriorated	0.0	Negative		
70	Interior	Rm. 5-Bathroom	С	Lower Cabinet	Wood	White	Deteriorated	-0.1	Negative		
71	Interior	Rm. 5-Bathroom	C	Countertop	Ceramic Tile	Pink	Deteriorated	>9.9	Positive		Not a Painted Surface
72	Interior	Rm. 6-Bedroom 2	A	Wall	Plaster	Purple	Deteriorated	0.2	Negative		
73	Interior	Rm. 6-Bedroom 2	В	Wall	Plaster	Purple	Deteriorated	-0.1	Negative		
74	Interior	Rm. 6-Bedroom 2	С	Wall	Plaster	White	Deteriorated	-0.1	Negative		
75	Interior	Rm. 6-Bedroom 2	D	Wall	Plaster	Purple	Deteriorated	-0.1	Negative		
76	Interior	Rm. 6-Bedroom 2	A	Baseboard	Wood	White	Deteriorated	0.0	Negative		
77	Interior	Rm. 6-Bedroom 2	A	Door Frame	Wood	White	Deteriorated	0.0	Negative		
78	Interior	Rm. 6-Bedroom 2	D	Window Frame	Wood	White	Deteriorated	0.4	Negative		
79	Interior	Rm. 6-Bedroom 2	D	Window Sash	VVood	White	Intact	0.4	Negative		
80	Interior	Km. 6-Bedroom 2		Celling	Plaster	VVhite	Deteriorated	0.0	Negative		
81	Interior	Rm. 6-Bedroom 2	В	Cabinet	Wood	White	Deteriorated	-0.2	Negative		
82	Interior	Km. /-Kitchen	A	vvall	Plaster	VVhite	Deteriorated	-0.1	Negative		
83	Interior	Rm. /-Kitchen	В	vvali	Plaster	White	Deteriorated	0.0	Negative		
84	Interior	Rm. /-Kitchen	C	vvall	Plaster	White	Deteriorated	0.2	Negative		
85	Interior	Rm. /-Kitchen	D	vvall	Plaster	White	Deteriorated	0.3	Negative		
86	Interior	Km. /-Kitchen	С	Door Frame	vvood	White	Deteriorated	-0.3	Negative		

	DETAILED XRF TESTING RESULTS										
17631 Cameron Lane, Huntington Beach, California											
Sample	Area	Room Equivalent	Side Tested	Component	Substrate	Color	Condition	Lead (mg/ cm ²)	Results	Quantities For Entire Area	Comments
87	Interior	Rm. 7-Kitchen	В	Window Frame	Wood	White	Deteriorated	0.6	Negative		
88	Interior	Rm. 7-Kitchen	D	Iron Board	Wood	White	Deteriorated	0.2	Negative		
89	Interior	Rm. 7-Kitchen		Ceiling	Plaster	White	Deteriorated	0.2	Negative		
90	Interior	Rm. 7-Kitchen	В	Upper Cabinet	Wood	White	Deteriorated	0.1	Negative		
91	Interior	Rm. 7-Kitchen	В	Lower Cabinet	Wood	White	Deteriorated	0.4	Negative		
92	Interior	Rm. 7-Kitchen	В	Countertop	Ceramic Tile	White/Black	Deteriorated	>9.9	Positive		Not a Painted Surface
93	Interior	Rm. 8-Laundry Room	A	Wall	Wood	White	Deteriorated	0.5	Negative		
94	Interior	Rm. 8-Laundry Room	В	Wall	Wood	White	Deteriorated	0.3	Negative		
95	Interior	Rm. 8-Laundry Room	С	Wall	Wood	White	Deteriorated	0.0	Negative		
96	Interior	Rm. 8-Laundry Room	D	Wall	Wood	White	Deteriorated	0.4	Negative		
97	Interior	Rm. 8-Laundry Room	В	Door	Metal	White	Deteriorated	0.5	Negative		
98	Interior	Rm. 8-Laundry Room		Ceiling	Wood	White	Deteriorated	0.0	Negative		
99	Interior	Rm. 8-Laundry Room	A	Shelf	Wood	White	Deteriorated	0.3	Negative		
100	Interior	Rm. 8-Laundry Room	D	Cabinet	Wood	White	Deteriorated	0.1	Negative		

<u>ALLSTATE SERVICES LLC.</u> <u>XRF CALIBRATION FORM</u>

Address:	17631 Cameron Lane	. Huntington Beach	. California
11001000	1,001 Cumeron Lune	, manungeen beach	, camornia

Device: RMD, LPA-1

Date: _____ April 3, 2020

Inspector: Stacey J. Milano

Calibration Check Tolerance Used: <u>0.7 mg/cm² - 1.3 mg/cm² (Inclusive)</u> Use Level III (1.02 mg/cm²) NIST SRM Paint film

First Calibration Check

<u>Time: 11:45 a.m.</u>

1 st Reading	2 nd Reading	3 rd Reading	1 st Average
0.7	0.8	0.6	0.7

Second Calibration Check

Time: 12:30 p.m.

1 st Reading	2 nd Reading	3 rd Reading	2 nd Average
0.7	0.7	0.7	0.7

Third Calibration Check (If Needed)

1 st Reading	2 nd Reading	3 rd Reading	3 rd Average

Time:

APPENDIX C FLOOR PLAN

APPENDIX D INSPECTOR/ASSESSOR CERTIFICATIONS

STATE OF CALIFORNIA DEPARTMENT OF PUBLIC HEALTH

LEAD-RELATED CONSTRUCTION CERTIFICATE

INDIVIDUAL:

CERTIFICATE TYPE:

Lead Inspector/Assessor Lead Project Designer Lead Project Monitor Lead Supervisor

NUMBER:	EXPIRATION DATE:
LRC-00000083	5/2/2020
LRC-00000084	5/2/2020
LRC-00000085	5/2/2020
LRC-0000082	5/2/2020

Stacey Milano

Disclaimer: This document alone should not be relied upon to confirm certification status. Compare the individual's photo and name to another valid form of government issued photo identification. Verify the individual's certification status by searching for Lead-Related Construction Professionals at www.cdph.ca.gov/programs/clppb or calling (800) 597-LEAD.

APPENDIX E CDPH FORM 8552 - LEAD HAZARD EVALUATION REPORT

LEAD HAZARD EVALUATION REPORT

Section 1 — Date of Lead Hazard Evaluation						
Section 2 — Type of Lead Hazard Evaluation (Check one box only)						
Lead Inspection Risk assessment Clearance Inspection Other (specify)						
Section 3 — Structure Where Lead Hazard Evaluation Was Conducted						
Address [number, street, apartment (if applicable)]		City	County	Zip Code		
Construction date (year) of structure	Type of structure Multi-unit building Single family dwelling	School or daycare	Children living in structure?			
Section 4 — Owner of Structure (if business/agency, list contact person)						
Name			Telephone number			
Address [number, street, apartment (if applicable)]		City	State	Zip Code		
Section 5 — Results of Lead Hazard Evaluation (check all that apply)						
No lead-based paint detected Intact lead-based paint detected Deteriorated lead-based paint detected No lead hazards detected Lead-contaminated dust found Lead-contaminated soil found Other Section 6 – Individual Conducting Lead Hazard Evaluation Integration Integration						
Address [number, street, apartme	ent (if applicable)]	City	State	Zip Code		
CDPH certification number	Sign	Stacey G	Milano	Date		
Name and CDPH certification number of any other individuals conducting sampling or testing (if applicable)						

Section 7 – Attachments

A. A foundation diagram or sketch of the structure indicating the specifc locations of each lead hazard or presence of lead-based paint;

B. Each testing method, device, and sampling procedure used;

C. All data collected, including quality control data, laboratory results, including laboratory name, address, and phone number.

First copy and attachments retained by inspector

Second copy and attachments retained by owner

Third copy only (no attachments) mailed or faxed to:

California Department of Public Health Childhood Lead Poisoning Prevention Branch Reports 850 Marina Bay Parkway, Building P, Third Floor Richmond, CA 94804-6403 Fax: (510) 620-5656